

We repair following hydraulic pumps and hydraulic motors

REXROTH

A10VSO16,18,28,45,63,71,100,140 / A10VG28,45,63
A11V040,60,75,95,130,145,160,190,200,260,A11VG50
A4VG28,40,56,71,90,125,140,180,250
A4VG/A4VTG/A10VG CHARGE PUMP
A4VS040,45,56,71,125,180,250,355,500 / A4V40,56,71,90,125,250
A8VO55, 80, 107,160, 200
A6VM28,55,80,107,160,172,200,250,355,500
A7V028,55,80,107,160,172,200,250,355,500
A2FO10,12,16,23,28,32,45,56,63,80, 107,125, 160,180,200,250
A2F12,23,28,55,80,107,160,225,250,500 / A2VK12,28,55,107,A2V225
A6V/A7V28,55,80,107,160,200,250,355, 500
A8V55,80,107,160

LINDE

HPR75,100,105 , HPR130,160
B2PV50,75,105,140, BPV35,50,70,BPR140, 186,260

KOMATSU

HPV95, HPV132 SERIES (PC200/220-6/7,
PC300-6/7, PC360-7, PC400-6/7) MAIN PUMP, PC210LC-7/8
HPV35,55,90,160(PC60/120/200-3/5, PC300/400-3/5 MAIN PUMP)
KMF90, 160, KPV90, 105

KYB

KYB PSV2-55(SH100-1/2,SH120-1/2)/62/63 (E120B/SH120)

KAWASAKI

K3V63,112,140,180 DT/BDT, K5V140,200
M2X63,96,120,146,150,170,210
NV64,84,111,137,172,270,UHO55-7,NX15, NVK45
KVC925,930,932, M5X130,180

EATON

3321,3331,3322,4621,4631,5421,5431,3932,
6423,7620,7621,78462, PVXS130,180

PARKER DENISON

F11-005,010,019, 110,150,250, F12-030,040,060,080,110
DENISON GOLD CUP SERIES P6, P7, P8, P11, P14, P24, P30

NACHI

NACHI PVD-00B/0B/1B/2B/3B, NACHI PSVD2 12/18/21/27

HITACHI

HPV091 (EX200-2/3, Double Pump), HPV091 (EX120-2, Single Pump)
HPV102, HPV118 (EX200-5/6,2X200-3)
HPV116, HPV145(EX200-1, EX300-1/2/3)

POCLAIN, HANSA TMP, BONDIOLI PAVESI, ROTARY POWER, HP ZIHYD, VERCO